



EXISTING CONDITION OF COLLAPSED OF ROOF



DORSEY MEMORIAL LIBRARY DURING THE 1940'S



EXISTING CONDITION OF NORTH WEST CORNER (PRIOR TO ROOF REMOVAL)



EXISTING CONDITION OF SOUTH WEST CORNER

REFER TO SHEET G2.1 FOR PHOTOS OF EXISTING AFTER SELECTIVE DEMOLITION AND SHORING OF EXTERIOR WALLS



DORSEY MEMORIAL LIBRARY DURING THE 1960'S




EXISTING INTERIOR CONDITION. WOOD FRAMING TO BE SALVAGED, REMILLED AND REPURPOSED IN RESTORATION



EXISTING WOOD TRUSSES TO BE SALVAGED. REMILLED AND REPURPOSED IN RESTORATION



EXISTING CONDITION OF TRANSOM OVER MAIN ENTRY. TRANSOM TO BE REFURBISHED/RESTORED TO HISTORIC CONDITION AND REINSTALLED.



CITY OF MIAMI
CAPITAL IMPROVEMENTS PROGRAM

PROJECT PHOTOS PRIOR TO SHORING & DEMO
DORSEY MEMORIAL LIBRARY RESTORATION

100 NW 17 STREET
MIAMI, FL 33136

DATE:	11/15/16	
DESIGN:	MCHA	
DRAWN:	C. Coule & W. Brown	
CHECKED:	J. Torres	
REVISIONS:		
No.	Date	Description
3	03/07/17	GENERAL REVISION

JOB No. B-30531
FILE:

ARCHITECT/ENGINEER:
Javier O. Torres
AR34538
M.C. Harry & Associates

SEAL

SCALE: AS SHOWN

SHEET No.

G2.0

PERMIT SET

5/31/2017 8:02:24 AM