



VIEW OF EXTERIOR BUILDING ALONG 17 STREET



VIEW OF EXTERIOR SOUTH WALL SHORING SEEN FROM INTERIOR



VIEW OF EXTERIOR NORTH WALL SHORING SEEN FROM INTERIOR



VIEW OF EXTERIOR EAST WALL SHORING SEEN FROM INTERIOR



SALVAGED 2X10'S AND RAFTER TAILS

PERMIT SET

CURRENT PROJECT EXISTING CONDITIONS

DORSEY MEMORIAL LIBRARY RESTORATION

CITY OF MIAMI

IMPROVEMENTS PROGRAM

REVISIONS:

No. Date Description

3 03/07/17 GENERAL REVISION

C. Coule & W. Brown

JOB No. B-30531

CHECKED:

ARCHITECT/ENGINEER:

HITECT/ENGINEER:

Javier O. Torres

AR94538

M.C.Harry & Associates

SCALE: AS SHOWN

SHEET No.

G2.1